



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT

I.GENERAL INFORMATION

Applicant	:	-	
Attn	:	-	
Supplier	:	-	
Factory	:	-	
Factory Address	:	Shangyu, Shaoxing, Zhejiang, China	
P/O No.	:	-	
P/O Quantity	:	3000pcs	
Model/Art/Style	:	-	
Product Description	:	Umbrella	
Inspection type	:	Pre-shipment Inspection	
Inspection method	:	☒ GWI-IC	
Inspection date	:	20XX-XX-XX	

II.INSPECTION RESULT (Details can be referred to corresponding sections in this report)

	INSPECTION ITEMS	Conformed	Not conformed	
1	Quantity	☐	☒	Refer to remark 1
2	Workmanship	☒	☐	
3	Product Description	☒	☐	
4	On site check	☒	☐	
5	Form of Packaging	☒	☐	
6	Shipping Mark	☒	☐	
OVERALL CONCLUSION		Not conformed, refer to remark 1		
FINAL DECISION		Client will make the final decision to reject or approve the conclusion		
Inspector	:	Lex Guo	Supervisor's signature	

Important:

The above reflects our findings at the time and place of inspection based on random- selected samples in accordance with the previously agreed random statistical sampling standards. Any "test" or "check" listed in our reporting should not be regarded as the laboratory testing since they are conducted in different way. The report/certificate does not mean releasing for shipment. This report/certificate does not exempt sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter.



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT

REMARKS:

1	The actual shipping quantity was 3156pcs instead of 3000pcs.
---	--

NOTE:

1	Carton no. was not assigned yet
2	All inspected samples were found worker number sewed on the product. 
3	Manufacturer did not agree with us to draw one production sample to GIS office for reference.
4	Manufacturer did not agree with us to draw defective sample to GIS office for reference.

GIS SAMPLE REPORT



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT**III.INSPECTION ITEM DETAILS (SECTION 1-6)****1. QUANTITY**

PO No.	Item No.	PO Qty		Shipment Qty		Packed Qty		Unpacked Qty	Unfinished Qty	Sampling Size		
		pcs	ctns	pcs	ctns	pcs	ctns	pcs	pcs	Packed		Not packed
										pcs	ctns	pcs
--	--	3000	-	3156	66	3156	66	0	0	125	8	0
Total		3000	-	3156	66	3156	66	0	0	125	8	0

2. WORKMANSHIP

Inspection Standard: ANSI/ASQC Z1.4		Defect classification	Cr	Ma	Mi
Sampling Plan:	Single, Normal	AQL	0	2.5	4.0
Inspection Level:	☒ G-II	Sample size	125	125	125
The defects which were found during inspection were listed as below:					
1	Broken stitches on tip		--	1	--
2	Uncut thread end		--	--	7
3	Poor printing on control button		--	--	1
Total Found:			0	1	8
Allowed:			0	7	10
Result			Pass		



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT

3. PRODUCT DESCRIPTION, STYLE AND COLOUR

3.1 Check against PO/photos/client's other's specification

The inspected samples were found similar to the description of PO/photos/other's specification.

3.2 Check against sample.

The inspected samples were found similar to the submitted sample by Client

3.3 Check against Instruction Manual

No instruction manual is included.

4. ON SITE CHECK

-	Check points	Criteria	Sample size	Comment
1	Basic function check	Open/close	(125Samples):	Conformed.
2	Water proof check		(5Samples):	Conformed.
3	Smell check	No unusual smell	(125Samples):	Conformed.
4	Rub and tape test on Logo	With water for 15s, 3M,810 tape	(5Samples):	Conformed.
5	Transportation Drop Test	10 Times 45.7cm	(1Canton):	Conformed.
6	Product weight check		(5Samples):	Conformed.
	Item	Specification on submitted sample		Actual
	--	387g		384, 382, 385, 383, 385g
7	Product measurement		(5Samples):	Conformed.
	Item	Specification on submitted sample		Actual
	--	54x58cm		54x58cm for all



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT

5. PACKAGING:

-Packing method

Outer Pack	Corrugated Paper Plies:	☐ Single Wall(3ply) ☒ Double Wall(5ply) ☐ Triple Wall(7ply)
	Fastening:	☒ Metal Staples ☐ Glue
	Sealed by:	☐ Kraft Tape ☐ Opaque Gummed Tape ☒ Transparent Gummed Tape
	Strapping:	☒ Nylon Band,3 pcs ☐ No
Inner packing	4 inner cartons (total 48pieces) per export carton.	
	12 poly bags per inner carton.	
Unit pack	Each unit with fabric cover and packed into open poly bag	

- Packaging information

Item No.	Carton size (spec from client)	Carton size marked on carton	Carton size (actual)	Carton Weight (spec from client)(kg)	Carton Weight marked on carton(kg)	Carton (actual)(kg)
	LxWxH (cm)	LxWxH(cm)	LxWxH(cm)	N.W/G.W	N.W/G.W	N.W/G.W
--	--	34x31x42	34x31x43	--	19.5	19.98

6. SHIPPING MARK:

Please refer to photos.



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT


PHOTO ATTACHMENT



1 warehouse



2 export carton



4 side mark



6 inner carton



7 open inner carton



8 packing



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



9 packing



10 packing



11 cover



12 product view-1



13 product view-2



14 product view-3



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



15 product view-4



16 product view-5




17 product view-6



18 product view-7



20 product view-9



21 product view-10



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



23 product view-12



24 product view-13




25 product view-14



26 product view-15



27 product view-16



28 product view-17



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



29 sample check (left is sample)-1



30 sample check (left is sample)-2



31 sample check (left is sample)-3



32 sample check (left is sample)-4



33 carton weight check



34 product size check-1



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



38 product weight check



39 tape test



41 water proof check



42 water proof check



43 defect-Uncut thread end-mi-1



44 defect-Uncut thread end-mi-2



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT



45 defect-Uncut thread end-mi-3



46 defect-Uncut thread end-mi-4



47 defect-Uncut thread end-mi-5



48 defect-Uncut thread end-mi-6



49 defect-Uncut thread end-mi-7



50 defect-poor printing on control button-mi



Report No : GIS-15080091

Report date : 20XX-XX-XX

INSPECTION REPORT

	Nil
51 defect-broken stitches on tip-ma	Nil

*****End*****

GIS SAMPLE REPORT