http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX

INSPECTION REPORT

I.GENERAL INFORMATION

Applicant	-	
Attn	-	A A A A A A A A A A A A A A A A A A A
Supplier	-	
Factory	-	
Factory Address		
P/O No.	-	
P/O Quantity	5620pcs	
Model/Art/Style	W3066-1; W3066-2; W3066-3; W3066M-4; Lens not chang size = W3054; Lens not changeable size = W3054; Lens W3052-2; New W3052-; W3052M-4; 1501-1; 1501-2; SQ50	not changeable size = W3054; W3052-1;
Product Description	Sunglass, cases	
Inspection type	Pre-shipment Inspection	
Inspection method	⊠ GWI-IC/ ⊠CKL-IC-0500	
Inspection date	20XX-XX-XX	

II.INSPECTION RESULT (Details can be referred to corresponding sections in this report)

	INSPECTION ITEMS		Conformed	Not conformed					
1	Quantity	:		\boxtimes	Refer to part 1-Quantity breakdown and remark 1,2				
2	Workmanship	:		\boxtimes	Refer to remark 3 and AQL table				
3	Product Description	:	\square						
4	On site check	:	\square						
5	Form of Packaging			\boxtimes	Refer to remark 1				
6	Shipping Mark			\boxtimes	Refer to remark 1				
_	VERALL ONCLUSION	:	Not conformed, refe	er to remark1,2,3	and beyond AQL limited.				
FI	NAL DECISION	:	Client will make the final decision to reject or approve the conclusion						
Inspector :			Kevin Zhang	Supervisor's signature : Gener					
<u>Im</u>	Important:								

The above reflects our findings at the time and place of inspection based on random- selected samples in accordance with the previously agreed random statistical sampling standards. Any "test" or "check" listed in our reporting should not be regarded as the laboratory testing since they are conducted in different way. The report/certificate does not mean releasing for shipment. This report/certificate does not exempt sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter.



Report No : GIS-18040239

Report date : 20XX-XX-XX

INSPECTION REPORT

REMARKS:

1	Upon arrival, the sunglasses were packed into the polybag and inner boxes, but have not been packed into cartons.								
2	For item 1501-1 and item 1501-2; no products were found in the factory. And for item SQ5641 (engrave Model W3008), only found 407pcs in the factory.								
3	For cases, all the inspected samples were found dirty mark on the surface. Details refer to below photos.								

NOTE:

1	Manufacturer did not agree with us to draw one production sample to GIS office for reference.
2	Manufacturer did not agree with us to draw defective sample to GIS office for reference.
	ATTENTION:
	If the quantity of finished products does not meet the requirement of standard for sampling checking, the final finding may not
	reflect the actual quality situation of whole batch, since the quality situation of unfinished parts could not be forecasted. Thus,
	the result may be invalid for whole batch.

http://www.gis-inspection.com

Report No : GIS-18040239

INSPECTION REPORT

Report date

: 20XX-XX-XX

III.INSPECTION ITEM DETAILS (SECTION 1-6)

1. QUANTITY

	Item No.			Shipment				Unpack	Unfinis	Sampling		Size
PO		PO	Qty	Qty		Packed Qty		ed	hed	Pac	ked	Not
No.								Qty	Qty			packed
		pcs	ctns	pcs	ctns	pcs	ctns	pcs	pcs	pcs	ctns	pcs
	W3066-1	30	-	-	-	0	0	30	0	0	0	1
	W3066-2	30	-	-	-	0	0	30	0	0	0	1
	W3066-3	30	-	-	-	0	0	30	0	0	0	1
	W3066M-4	30	-	-	-	0	0	30	0	0	0	1
	Lens not changeable size = W3054	100	-	-	-	0	0	100	0	0	0	4
	Lens not changeable size = W3054	100	-	·	-	0	0	100	0	0	0	4
	Lens not changeable size = W3054	300	-	-	-	0	0	300	0	0	0	13
	Lens not changeable size = W3054	100	-	-	-	0	0	100	0	0	0	4
	W3052-1	125	-	-	-	0	0	125	0	0	0	5
	W3052-2	125	-	-	-	0	0	125	0	0	0	5
	New W3052-	225	-	-	-	0	0	225	0	0	0	10
	W3052M-4	125	-	-	-	0	0	125	0	0	0	6
	1501-1	500	-	-	-	0	0	0	0	0	0	0
	1501-2	200	-	-	-	0	0	0	0	0	0	0
	SQ5641 (engrave Model W3008)	600	-	-	-	0	0	407	0	0	0	18
	cases	3000	-	-	-	3000	15	0	0	127	4	0
	Total	5620	-	-	-	3000	15	1727	0	127	4	73

Note: Upon arrival, only 3000 pcs (53%) / 15 cartons were packed, 1727 pcs were unpacked. the rest were not in the factory.

2. WORKMANSHIP

http://www.gis-inspection.com

Report No :

GIS-18040239

INSPECTION REPORT

Report date 20XX-XX-XX :

Inspection Standard: AN	Cr	Ма	Mi					
Sampling Plan:	Single, Normal	AQL	0	2.5	4.0			
Inspection Level:	🖾 G-11	Sample size	200	200	200			
The defects which were	found during inspection were listed as below:							
Item: Lens not changeab	le size = W3054							
Gap			-	1	-			
Item: Lens not changeab	le size = W3054							
Glue mark			-	-	4			
Item: W3052-1								
Leg turned u		-	1	-				
Item: New W3052-								
Leg turned u	-	2	-					
Scratch mar	Scratch mark							
Glue mark	Glue mark							
Item: cases								
Hair in case			-	1	-			
Missing glue	Missing glue							
Glue mark	-	-	4					
	0	6	18					
	0	10	14					
		Result	Fail					



Report No:GIS-18040239Report date:20XX-XX-XX

INSPECTION REPORT

3. PRODUCT DESCRIPTION, STYLE AND COLOUR

3.1 Check against PO/photos/client's other's specification

The inspected samples were found similar to the description of PO/photos/other's specification.

3.2 Check against sample.

No submitted sample was provided by applicant or Vendor for style & color comparison

3.3 Check against Instruction Manual

No instruction manual is included.

4. ON SITE CHECK

-	Check points	Criteria	Sample size	Comment		
1	Basic function check		(200Samples):	Conformed.		
2	Product weight check		(3Samples/item):	Conformed.		
	Item		Specification	Actual(g)		
	W3066-1			24;23;24		
	W3066-2			24;24;24		
	W3066-3			22,22,23		
	W3066M-4	W3066M-4		23,23,23		
	Lens not changeable size =	= W3054		25,25,25		
	Lens not changeable size =	= W3054		24,24,24		
	Lens not changeable size =	= W3054		23,24,24		
	Lens not changeable size =	= W3054		24,24,24		
	W3052-1			28,27,28		
	W3052-2			25,25,26		
	New W3052-	New W3052		24,23,24		
	W3052M-4			24,25,24		
	SQ5641 (engrave Model	W3008)		26,25,26		
	cases			115,116,116		
3	Product measurement		(3Samples/item):	Conformed.		

http://www.gis-inspection.com

Report No

:

:

GIS-18040239

INSPECTION REPORT

Report date

20XX-XX-XX

Item	Specification	Actual(cm)
W3066-1		14x14x4.8
W3066-2		14.5x14.5x4.8
W3066-3		14x14x4.8
W3066M-4		14.5x14.5x4.8
Lens not changeable size = W3054		14x14.5x5
Lens not changeable size = W3054		13.5x14.5x5
Lens not changeable size = W3054		13.5x14.5x5
Lens not changeable size = W3054		13.5x14.5x5
W3052-1		14.5x14.5x4.9
W3052-2		14.3x14.5x4.9
New W3052-		14x14.5x4.9
W3052M-4		14x14.5x4.9
SQ5641 (engrave Model W3008)		14.5x14.5x5
cases		16x6.4x6

http://www.gis-inspection.com

Report No : GIS-18040239

INSPECTION REPORT

Report date : 20XX-XX-XX

5. PACKAGING:

-Packing method (cases)

Outer Pack	Corrugated Paper Plies:	Single Wall(3ply)	☐ Double Wall(5ply) ☐ Triple Wall(7ply)				
	Fastening:	Metal Staples	Glue				
	Sealed by:	 □ Kraft Tape □ Opaque Gummed Tape □ Transparent Gummed Tape 					
	Strapping:	🛛 Nylon Band,3 pcs	□ No				
	10 inner boxes (total 200pieces) per export carton.						
Inner packing	20 pieces solid color and solid size per inner packed.						
Unit pack	Unit packed into a polybag.						

- Packaging information

Item No.	Carton size (spec from client)	Carton size marked on carton	Carton size (actual)	Carton Weight (spec from client)(kg)	Carton Weight marked on carton(kg)	Carton (actual)(kg)
	LxWxH (cm)	LxWxH(cm)	LxWxH(cm)	N.W/G.W	N.W/G.W	N.W/G.W
W3066-1						
W3066-2						
W3066-3						
W3066M-4						
Lens not changeable size = W3054						
Lens not changeable size = W3054						
Lens not changeable size = W3054						
Lens not changeable size = W3054						
W3052-1						
W3052-2						
New W3052-						
W3052M-4						
1501-1						
1501-2						
SQ5641 (engrave Model W3008)						
cases		36x33x36	36x33x36			-/24.06

Discrepancy was found, please refer to remark 1

6. SHIPPING MARK:

Please refer to photos.

Discrepancy was found, please refer to remark 1



http://www.gis-inspection.com

Report No :

GIS-18040239

Report date : 20XX-XX-XX

INSPECTION REPORT



Address: Floor10, Building C, Unis Sci-Tech Park, No. 30 Wulongjiang Road, High-Tech Zone, Fuzhou, Fujian, China Tel: +86-591-87562601. Fax: +86-591-87513656. Email: service@gis-inspection.com. Version: 2.0 Page 8 of 30

2_unit packing-1

1_products packing



http://www.gis-inspection.com

Report No : GIS-18040239





http://www.gis-inspection.com

20XX-XX-XX

Report No : GIS-18040239

INSPECTION REPORT

Report date :





http://www.gis-inspection.com

Report No : GIS-18040239

INSPECTION REPORT

Report date : 20XX-XX-XX



http://www.gis-inspection.com

Report No

Report date

: GIS-18040239

20XX-XX-XX

:

INSPECTION REPORT

2_W3066-2 1_unit packing-1 2_unit packing-2 3_unit packing-3 4_unit view-1 5_unit view-2 6_unit view-3



http://www.gis-inspection.com

Report No : GIS-18040239

:

INSPECTION REPORT

Report date

20XX-XX-XX



Address: Floor10, Building C, Unis Sci-Tech Park, No. 30 Wulongjiang Road, High-Tech Zone, Fuzhou, Fujian, China Tel: +86-591-87562601. Fax: +86-591-87513656. Email: service@gis-inspection.com. Version: 2.0 Page 13 of 30



http://www.gis-inspection.com

20XX-XX-XX

Report No : GIS-18040239

INSPECTION REPORT

Report date :





http://www.gis-inspection.com

GIS-18040239 Report No : :

Report date

20XX-XX-XX

INSPECTION REPORT



1_unit packing-1

2_unit packing-2



http://www.gis-inspection.com

Report No : GIS-18040239





GIS-18040239 Report No :

INSPECTION REPORT

Report date

: 20XX-XX-XX



13_unit view-11



http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX





http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX





http://www.gis-inspection.com

20XX-XX-XX

Report No :

:

Report date

GIS-18040239

INSPECTION REPORT

CE W3055 POLARIZED CAI.3 HANDMADE 11_unit view-9 12_unit view-10 14_weight check 13 unit view-11 5 6 7 8 101234 9

16_size check-2

15_size check-1



http://www.gis-inspection.com

Report No : GIS-18040239

INSPECTION REPORT

Report date : 20XX-XX-XX





http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX





GIS-18040239 Report No :

INSPECTION REPORT

Report date

: 20XX-XX-XX



5_unit view-3



http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX

INSPECTION REPORT



11_unit view-9

12_unit view-10



GIS-18040239 Report No :

:

20XX-XX-XX

Report date

INSPECTION REPORT



5_inner box

6_inner box open view



http://www.gis-inspection.com

Report No : GIS-18040239





http://www.gis-inspection.com

GIS-18040239 Report No :

:





http://www.gis-inspection.com

Report No : GIS-18040239





Report date

http://www.gis-inspection.com

20XX-XX-XX

GIS-18040239 Report No : :

INSPECTION REPORT



33_defect-missing glue-mi

34_defect-missing glue-mi



http://www.gis-inspection.com

Report No : GIS-18040239

Report date : 20XX-XX-XX

INSPECTION REPORT

